

Laser Transfer Paper for Dark Colored Fabrics for use with Copiers and Printers that do NOT use Fuser Oil –Cold Peel

ITEMS YOU WILL NEED

- Black or dark color 100% Cotton fabric garment.
- Heat Press
- Parchment paper
- Store unused transfer papers in a resealable poly bag in a flat, cool, dry area.

STEP ONE – PRINTING YOUR IMAGE

- 1) Bring paper to room temperature before printing.

Print image/design on paper. DO NOT mirror or flip image prior to printing.

Recommended print settings:

HP – Paper Type: Extra Heavy
OKI – Weight: Ultra Heavy

STEP TWO – TRANSFERRING YOUR IMAGE

HEAT PRESS

- 1) Preheat press to 300° - 330° F.
- 2) Press garment for 3-5 seconds to release moisture and remove wrinkles.
- 3) Peel liner from back of printed transfer. Place printed transfer onto the garment with the print side up and place the parchment paper on top of the printed transfer.
- 4) Set pressure to 40psi for best results.
- 5) Press for 10-15 seconds.
- 6) COLD peel is recommended, wait for the transfer to cool for at least two minutes and then remove the parchment paper using a smooth, even motion.

WASHING INSTRUCTIONS

- Turn the garment inside out.
- Wash in COLD water.
- Use a mild detergent for best results.
- Do not use bleach or bleach alternative detergents.
- Remove the garment promptly from the washer.
- Dry on LOW temperature.



NOTICE: The information contained in this correspondence is confidential and is for the use of the intended recipient. If you are not the intended recipient, any disclosure, copy, distribution or other use of this information is STRICTLY PROHIBITED. If you have received this communication in error, please immediately contact the sender and destroy the material in its entirety, whether in electronic or hard copy format. Thank you.